




BUILDING SAFETY REPORT FOR THE YEAR

The school building of **CHINMAYA VIDYALAYA, UHF Nauni** was inspected by me with the concerned Junior Engineer of **Oachghat section**. The Building has neither been designed nor constructed by this department. No earthquakes resistance norms have been adopted for this building. No structural drawing approved by the competent Government Agency has been produced. The structure is Non Engineering structure. Hence the structural safety of this building cannot be ensured specially from earthquake point of view. The building is complete up to Ground level + 2 floors in (Block -I and Block -2) and Only Ground floor in Block -3. However, as per visual inspection of the building appears to be safe at present only. *and structures found fit for habitation for next year*
Dated:-23.06.2026

Place:-Oachghat


Junior Engineer,
Section Oachghat
Sub Div, HPPWD
Oachghat


Assistant Engineer,
B&R Sub Division,
HP PWD Oachghat


Executive Engineer,
Solari B & R Division,
H.P.P.W.D. Solari

**HIMACHAL PRADESH
PUBLIC WORKS DEPARTMENT**

No. PW/SD/CB/WA-I(Building Safety)-2026-27 4430-3/Dated:- 03-07-26

To,

✓ The Principal,
Chinmaya Vidyalaya,
UHF Nauni, Tehsil & Distt. Solan HP.

Subject:- Issuance of Building Safety Certificate in respect of Chinmaya Vidyalaya UHF Nauni, Tehsil & Distt. Solan HP.

Reference:- Your office letter No. CVN 26/8411 dated 04/06/2026.

As desired vide your office letter under reference, enclosed please find herewith the building safety certificate duly Countersigned by the undersigned for taking further necessary action.

Encl:- As above.

Executive Engineer,
Solan B&R Division,
HP.PWD. Solan

Copy to the Assistant Engineer B&R Sub-Division HP.PWD.
Oachghat for information with reference to above.

Executive Engineer,
Solan B&R Division,
HP.PWD. Solan.